Nº. 4632 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR

DATE INSPECTED $5-23-44$	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 7 dech
WAS LATERAL AT CURB? Yes	
WAS ATTACHED TO MAIN <u> ソペラ</u>	NAME OF CONTRACTOR Blueslone
SHOW BY DIAGRAM RELATION OF LA	ATERAL TO WALL OF BUILDING SERVED.
Johnson, S.	
Andrew Telephone (1997) we expend to be a compared to the comp	Carlande Constant and Constant a
	ververe statice, to the atrastic saturation of the
	MK
0 60	6
SIGNED John Chron	FILED AT ENGINEER'S OFFICE
INSPECTOR FOR C	
REMARKS:	3-124-14 DOC

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

			1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1			Langer and the
			o padeojak v <u>oj</u> eb	MASSILLON,	Эню,	/2#\$ /
	RECEIVED OF	Description	11/11			FEE OF \$7**
		THA ROAD THE RESERVED	ការ ខេត្តការស្នេក ស្រែក្	The second secon	ili danc	इक्षा भेरी अभेक्षा है।
FOR 1	WHICH PERMIS	SION IS GRANT	red	- American		
TO TA		Light of the said		ER, ON THE	inish (6) co	are falkas il Boatta Sabilie
OF_	JAK-na	ohiouilie a	o Biyetti iar	YPE OF STREET.		de Yerwone III A
\overline{U}	REMISES BEING	LOT No.	5345		use No/	324
				ion No. 2222		w wie City College

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323. DULY PASSED BY THE CITY COUNCE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.