FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 7-29-46	IF SO HOW AND LOCATION FROM 236
HOUSE NO.	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? NO.	Rluestone
	TERAL TO WALL OF BUILDING SERVED.
10" Ma, 10" X 8°	n Line
그렇지만 한 번째 하는 어떻게 되었다는 그는 사람이 되었다면 가지 수 있다. 그리고 하고의	Reducer- at Manna was ze or sign
	7'Deep / 16' Main Jewe
SIGNED R. T. June L. RISPECTOR FOR CI	FILED AT ENGINEER'S OFFICE
REMARKS:	Landisent of confine a public to diese 8-9-76

Nº 4649

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	ner Berend Brigger de en die Abertan verwicken der Abertan 18 februarie in der Abertan	Massillon, Ohio,	
RECEIVED OF	ha hada hada hada ha	FEE OF \$	76
FOR WHICH PERMISSION		CAS ATTACHED CHASE	
TO TAP		R, ON THE	
THE PREMISES BEING LOT	and the same of th	PE OF STREET	
WORK TO BE DONE IN A RULES OF THE DEPARTME		CE No. 2323, DULY PASSED BY THE CITY CO	NUC

Note. This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.