

N^o 4658

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 3-23-46

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM Lot #26 used

HOUSE NO. 1911

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 220' west of lot #2 7' Deep

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Remley


SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Tremont Ave S.W.



0

220°



SIGNED John Ehmer

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

OK. 4-8-46 Doc

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 4658

PERMIT TO TAP SEWER

MASSILLON, OHIO, 3/9RECEIVED OF Ralph H. WebbFEE OF \$ 2.00FOR WHICH PERMISSION IS GRANTED Ralph H. WebbTO TAP SanitarySEWER, ON THE SouthOF Tremont Ave. St.AVE., TYPE OF STREET pavedTHE PREMISES BEING LOT NO. 07 267HOUSE NO. 1911

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
 RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Raymond Remley

Note. This permit covers work outside of building only. Any work
 walls of building is subject to Massillon Board of Health Regulations.