

14-13

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Nº 4664

DATE INSPECTED 9-16-48

**IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM**

HOUSE NO. 1320

**DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH**

SIZE OF PIPE USED 6"

192' 7' deep


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Remley.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Pearl Ave S.E.



SIGNED

John Chmura
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

9-30-48

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 4664

PERMIT TO TAP SEWER

MASSILLON, OHIO, 3/11RECEIVED OF Dora BluestoneFEE OF \$ 2.00FOR WHICH PERMISSION IS GRANTED Dora BluestoneTO TAP SanitarySEWER, ON THE northOF Pearl StAVE.,
ST.,TYPE OF STREET driftTHE PREMISES BEING LOT NO. 5366HOUSE NO. 1320

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Remotex

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.