

5.K3-P

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
N^o 4686 AND SIGNED WHEN RETURNED

DATE INSPECTED 6-2-46

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

208

HOUSE NO. 182

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

208

3' deep

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR


Keucher

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lake Ave. N.E.



208 3' deep



SIGNED

John Ebner
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

670-46 Hnd

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 4686

PERMIT TO TAP SEWER

3/18

MASSILLON, OHIO,

RECEIVED OF

C. Keuper

FEE OF \$2.00

FOR WHICH PERMISSION IS GRANTED

Same

TO TAP

San

SEWER, ON THE

N.

OF

Lake N.E.

AVE.,
ST.

TYPE OF STREET

Oiled

THE PREMISES BEING LOT NO.

Pl. 159

HOUSE NO.

182

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

C. Keuper

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.