

N<sup>o</sup> 4687

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED 5-25-46

IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM "Y" in Main 214' from M.

HOUSE NO. 1206

DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH Approx. 5' Deep at Curb  
Curb not in and fill to  
made when lateral was la


SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN Yes.

NAME OF CONTRACTOR Keuper

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED R. F. Smyler  
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS: OK 5-28-46 Doc

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 4687

PERMIT TO TAP SEWER

3/18

MASSILLON, OHIO,

RECEIVED OF

C. Keuper

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

Same

TO TAP

San

SEWER, ON THE

OF

3rd N. E.

AVE.,  
ST.,

TYPE OF STREET

Art

THE PREMISES BEING LOT No.

10583

HOUSE No.

1206

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL  
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

C. Keuper

Note. This permit covers work outside of building only. Any work  
walls of building is subject to Massillon Board of Health Regulations.