

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 5-3-46

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 838

SIZE OF PIPE USED 6"


UP DOWN DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? Yes.

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED



SIGNED

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

5-8-46 *Frank*

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 4696

PERMIT TO TAP SEWER

MASSILLON, OHIO, 3/27RECEIVED OF L. H. SmartFEE OF \$ 2FOR WHICH PERMISSION IS GRANTED John HenzelTO TAP SanSEWER, ON THE N.OF Lake N-EAVE.,
ST.TYPE OF STREET AlledTHE PREMISES BEING LOT NO. 8541-42HOUSE NO. 838

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
 RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Smart

Note. This permit covers work outside of building only. Any work
 walls of building is subject to Massillon Board of Health Regulations.