

# **FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED**

**Nº 4744**

**DATE INSPECTED** 6-13-46

**IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM**

**HOUSE NO.** \_\_\_\_\_

**DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH**

**SIZE OF PIPE USED** \_\_\_\_\_


**WAS LATERAL AT CURB?** \_\_\_\_\_

**WAS ATTACHED TO MAIN** \_\_\_\_\_

**NAME OF CONTRACTOR**

Kernley

**SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.**



**SIGNED**

R. J. Snyder

**INSPECTOR FOR CITY**

**FILED AT ENGINEER'S OFFICE**

6-19-46 Hunk

**REMARKS:**

18" pipe used as Auxiliary M.H. C.I. Lines from Bldg. empt into this M.H. Conn. from here to bottom of Trunk Sewer M.H.

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N<sup>o</sup> 4744

## PERMIT TO TAP SEWER

MASSILLON, OHIO, 6/1

RECEIVED OF

R. Remley

FEE OF \$2

FOR WHICH PERMISSION IS GRANTED

Ohio Can &amp; Crown

TO TAP

San

SEWER, ON THE

E. CHODATA SAW

OF

16th SE

AVE.  
ST.

TYPE OF STREET

dirt

THE PREMISES BEING LOT NO.

PL 92.381

HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL  
 RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

R. Remley

Note. This permit covers work outside of building only. Any work  
 walls of building is subject to Massillon Board of Health Regulations.