

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
Nº 4758 AND SIGNED WHEN RETURNED**

DATE INSPECTED 5-18-46

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1007

SIZE OF PIPE USED 4

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

35' 5'-6" Deep

WAS LATERAL AT CURB? Yes


WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

Adams.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Relaid 18' pipe from
Curb toward bldg.



Existing 4" Lateral

Side Walk

S. Curb Line



SIGNED

R. J. Angler
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

Andrews N.E

6-26-46

REMARKS:

Pipe between curb and side walk and under walk had set
and were low. Also joints were bad. Relaid this section.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 4758

PERMIT TO TAP SEWER

MASSILLON, OHIO, 4/25 1925RECEIVED OF Robert AdamsFEE OF \$ 2.00FOR WHICH PERMISSION IS GRANTED Church of GodTO TAP San

SEWER, ON THE

OF Andrew St.AVE.,
ST.,TYPE OF STREET AlidTHE PREMISES BEING LOT NO. 2834HOUSE NO. 1007

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Adams

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.