

Nº 4762

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 7-3-46

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

134

HOUSE NO. 617

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

134-

5' deep

SIZE OF PIPE USED 4"

WAS LATERAL AT CURB? Yes



WAS ATTACHED TO MAIN Yes.

NAME OF CONTRACTOR

Adams.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

624 ST. S.W.



SIGNED

John Elmer

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

Relay job

OK 7-15-46

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 4762

PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/2RECEIVED OF Robert AdamsFEE OF \$ 2.00FOR WHICH PERMISSION IS GRANTED Antonio RequenaTO TAP SanSEWER, ON THE 7thOF 6th StAVE.,
ST.,TYPE OF STREET PavedTHE PREMISES BEING LOT NO. 1872HOUSE NO. 617

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Robert Adams

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.