

Nº 4769

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

11
2
1

DATE INSPECTED 7-23-46

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 409

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

29' 10 ft. deep

WAS LATERAL AT CURB? Yes "X" on Curb.


WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

90° Bend used at bldg.
to meet soil pipe.
Lat. 10' deep at curb. Used
45° Bend to come up. Then
4' straight pipe. Then 45°
Bend to turn toward
exist. soil pipe under footer.



W. Curb N. Eri

Main Sew

SIGNED

R. F. Snyder
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

OK 7-23-46 D.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 4769

PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/22

RECEIVED OF

Raymond A. Remley

FEE OF \$2

FOR WHICH PERMISSION IS GRANTED

Stark Glass Co

TO TAP

sanitary

SEWER, ON THE

west

OF

Eric H H

AVE.,
ST.

TYPE OF STREET

paved

THE PREMISES BEING LOT No.

Parad property

HOUSE No.

409

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Raymond A. Remley

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.