

14-

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

N^o 4774

DATE INSPECTED 5-29-46

IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 201

HOUSE NO. 339

DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 201 7' 6" deep

SIZE OF PIPE USED 6"


WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN No

NAME OF CONTRACTOR Keuffer

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Delaware Ave N.E.



SIGNED John Elmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE OK Hm 8-1

REMARKS: _____

John - This is where 3 lots were split up into 2 lots S. side of Street.
No. 4774

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

20
15
12

MASSILLON, OHIO, 7/29
RECEIVED OF Chas. Kasper FEE OF \$ 2
FOR WHICH PERMISSION IS GRANTED per se
TO TAP San. SEWER, ON THE 77
OF Gettysburg AVE., TYPE OF STREET St.
THE PREMISES BEING LOT NO. 10572-91 HOUSE NO. 339
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR C. Kasper

Note. This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.