## No. 4775 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR

DATE INSPECTED 7-30-	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
, HOUSE NO	DISTANCE FROM FIRST MANHOLE	ro engeneg
SIZE OF PIPE USED 6	CURB LINE AND DEPTH	z 7-6 Deep
WAS LATERAL AT CURB? メム		Remley
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR DF LATERAL TO WALL OF BUILDING !	
	7' Dec 0 1 1	化设备 医肾色管肠膜炎 医髓管
n Miritary de la		Z = 7 2 Deep
	S. Curb Line	4 6129.1
	Main Sewer Stratford N.E.	
SIGNED R.T. Dw	VVV FILED AT FNO	SINEER'S OFFICE
NSPECTOR I	CITY CITY	indirect to elimon
REMARKS:		2 (4)

## Nº 4775

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	हरू कर है है जिस्से के स्वाहर के कि उन्हों के लिए हैं कि उन्हों है	, ,	Ġ
	インク	Massillon, Ohio,	
7	11.(1000		
RECEIVED OF	The second of the second of the second	FEE OF S	
	7/2	1. M. El garber	
FOR WHICH PERMIS	SION IS GRANTED	THE RESERVE OF THE PROPERTY OF	<u>.</u>
	Alecandorios so seas	All	
TO TAP	S/OHUS TO MAY SEW	VER, ON THE	_
Mish	LI DO PAVE	TYPE OF STREET	
OF	The state of the s	그리고요 그들은 그는 사람들은 그는 사람들이 들어 하고 있는 것이 되었다. 그 사람들의 학생	
	Commence of the second	8347 HOUSE NO. 1129	
THE PREMISES BEIN	S LOT NO.	HOUSE NO.	
WORK TO BE DONE	IN ACCORDANCE WITH ORDINA	NCE NO. 2323, DULY PASSED BY THE CITY COU	N

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY PASSED BY THE CITY COUNC RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR A CANTELLY

Note. This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.