

Nº 4787

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 8-30-46

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

45

HOUSE NO. 121

SIZE OF PIPE USED 6" 4/4

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

45

8'6" deep

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR


Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

26TH ST., S.E.

N. →

8'6" deep



SIGNED

John E. Hauer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

9-10-46

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 4787

PERMIT TO TAP SEWER

MASSILLON, OHIO, 8/29

RECEIVED OF R. R. Ramsey

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED W. E. France

TO TAP SEWER

SEWER, ON THE 7th

OF 21st St.

AVE.,
ST.,

TYPE OF STREET Local

THE PREMISES BEING LOT NO. 3170

HOUSE NO. 124

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR R. R. Ramsey

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.