

See Notes

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 4788

DATE INSPECTED 9-4-46

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 424

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE TO
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN


NAME OF CONTRACTOR

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

See Sketch

Remley

No basement under
east end of bldg.
Tapped existing lateral
outside of bldg.
instead of inside.



SIGNED

R. F. Snyder

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

This connection for toilet and wash bowl in addition to what is already in this Bldg.

Main Sewer in McKinley S.

9-12-46

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 4788

PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/3RECEIVED OF P. R. RemyFEE OF \$ 2FOR WHICH PERMISSION IS GRANTED Pete B. CollinsTO TAP SanSEWER, ON THE 7thOF W. H. ThomasAVE.,
ST.,TYPE OF STREET AlbionTHE PREMISES BEING LOT NO. 446HOUSE NO. 4244080

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR P. R. Remy

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.