FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9-12-46	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		8'dech
HOUSE NO. 1327			
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	as coverage	
WAS LATERAL AT CURB?	n filit ininish in lina ku inmanish sesi in semesan se Tangan	en elektron in den elektrone en elektrone en el	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR \underline{B}	lueston.	٠. ا
SHOW BY DIAGRAM RELATION OF LAT	Charles the form of the control of t	Contraction with the contraction of the contraction	
Woodland. Are S.L		4	
		6 deof	
	enschaft is de specielle de se	Harris de la Arriga	
			8.deep
			01.11111
SIGNED INSPECTOR FOR CIT	FILED AT EN	Gineer's office Milital to elibys	11/1914 to

 N_0

4794

No. 4794 PERMIT TO TAP SEWER

	MASSILLON ONO
RECEIVED OF	MASSILLON, OHIO,
The secretary manufactures where the secretary manufactures are secretary manufactures and secretary manufactures are secretarily manufactures are secr	<u> Principalită în la replacula de proposită de proposită în la replacula d</u>
	ON THE
Tan estas peralaina no illest que unema	FOR STREET
THE PREMISES BEING LOT NO.	, House No/327
WORK TO BE DONE IN ACCORDANCE WITH ORDINANC	F No. 2323 DULY PASSED BY THE CITY COUNC
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR MANAGEMENT	outres.

Note. This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.