

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
Nº 4796 AND SIGNED WHEN RETURNED**

DATE INSPECTED 9-12-46

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

219- 8' deep

HOUSE NO. 1322

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB?

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR Bluestone

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Woodland Ave. S.E.



M.H.



219

8' deep

131

SIGNED

John Elmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

9/14/46

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 4796

PERMIT TO TAP SEWER

MASSILLON, OHIO, 9/11

RECEIVED OF

Robert Henry

FEE OF \$2

FOR WHICH PERMISSION IS GRANTED

Robert Henry

TO TAP

Sewer

SEWER, ON THE

north

OF

Woodland E

AVE.
ST.

TYPE OF STREET

dirt

THE PREMISES BEING LOT NO.

~~5375~~ ~~5376~~
5375 - 5376

HOUSE NO.

~~1311~~ 13

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

In Bluestone

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.