

Nº 4847

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 12-3-46

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1219

SIZE OF PIPE USED 8"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

see sketch on 8½" x 11" sheet

SIGNED R. J. Snyder
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 12/5/46

REMARKS: _____

Nº 4847

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO.

RECEIVED OF

Acme Dairy Store

FEE OF \$2⁰⁰

FOR WHICH PERMISSION IS GRANTED

Raymond Remley

TO TAP

Sanitary

SEWER, ON THE

South

OF

Lin Hay E + Pine

AVE., TYPE OF STREET

same as

THE PREMISES BEING LOT NO.

1492

HOUSE NO.

1512 19

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2223, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Raymond Remley

Note. This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.

RECEIVED 101 PERMITS 4841 4848

R. Remley: Contr.

Inst. 12-3-46

R. F. Snyder

4847

Storm Drain

6" Pipe

11'-6" Deep at Bldg.

6" Pipe Storm Lines
Roof Drains

New Catch Basin

Acme Dairy
Plant.

San. M.H.

10' Deep

8" Pipe

8" Pipe

Storm Sewer

on W. Edge of M.H.

6' Deep

Ex. San.

M.H. 6' 5" Deep

Exist. 8" San. Sewer

Lincoln Way E.

Curb

Existing 12" Storm Sewer behind Curb

Connected to 8" Conn.

5' Deep