

Nº 4896

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 11-19-46

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1819

From M.H. #2

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

60'


8' Deep

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR Boger

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED R. F. Snyder

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

2-5-47

REMARKS:

House not built
cellar dug but was filled up by
order of Director Young by Diana
fall of '1950
3-21-51

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 4896

PERMIT TO TAP SEWER

MASSILLON, OHIO, 1-7-47.

RECEIVED OF

Ray Tehnof

FEE OF \$ 2.4

FOR WHICH PERMISSION IS GRANTED

Same

TO TAP

San

SEWER, ON THE

South

OF

Stoner

AVE.,
ST.

TYPE OF STREET

Dirt

THE PREMISES BEING LOT NO.

8072

HOUSE NO.

1819

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Boyer

Note. This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.