FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5 7 7	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO	그런 그 맛있다 얼마를 잃었다는데 하는데 되는데, 다른 아이를 걸맞는
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH DISTANCE FROM FIRST MANHOLE 170 5 DECP
WAS LATERAL AT CURB? Yes	NAME OF CONTRACTOR A/brecht
SHOW BY DIAGRAM RELATION OF	F LATERAL TO WALL OF BUILDING SERVED.
	Foundation not started
	16' & 6' Deep
osted Alim Tri de Carres Anna Erre.	100 00000000 000 50 Deep - 10 100 00 00 00 00 00 00 00 00 00 00 00
	Main Sewer in Hawthorn
SIGNED N. J.	FILED AT ENGINEER'S OFFICE 5/23/47
HISPECTOR	or city - exacts of casts and state was obtained to the company of the casts of the
REMARKS:	

Nº 4934 PERMIT TO TAP SEWER

		i Romanda ozek Wo	to de la compania de La compania de la co		D/ZEMERTAGE
		ži nivos Voniks	· ·	sillon, Ohio,	/5
	RECEIVED OF	K. C	elkr	each'	FEE OF S
		Mauri	ce L	6	
FOR W	HICH PERMISSION IS	S GRANTED	\longrightarrow		ilasyyas baya in
TO TAP	, Jan	Amasikoo jeb	SEWER, ON	THE 77.050	eleganta garante Hijarap attaques
OF A	Towthe	rno M	VES TYPE OF	ro Montalia mar	20
THE PE	REMISES BEING LOT	1100	grand the second	House No.	20
Work	TO BE DONE IN ACC	CORDANCE WITH C	RDINANCE NO.	2323. DULY PASSED	BY THE CITY COUN
Rules	OF THE DEPARTMEN	NT OF PUBLIC SERV	1CE.		
NAME	OF CONTRACTOR	<u> </u>	1 1 1	LUCK	

Note. This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.