FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 6-16-47	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	56	Topping Hub
HOUSE NO. 807	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	-a-pentessin-	
WAS LATERAL AT CURBI NO WAS ATTACHED TO MAIN TAPPEA	NAME OF CONTRACTOR	Adams	
SHOW BY DIAGRAM RELATION OF LAT	L'Deep	SERVED.	3 rd st.NW
SIGNED R. J. Shungdu	tate N.W. FILED AT ENG	12 54 Decp Topped:	oc Hazo
REMARKS:	rycholetarini sa 1920 i ili sa sene a kanto a sa kalabata da la kalabata da la kalabata da la kalabata da la ka Barangarangan barangan kalabata da la kalabata da k		

4950

Nº 4950

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	minimum minimum isaa ka k	Massillon, Ohio,	728
0	RECEIVED OF TAKENT	adams	FEE OF \$2
1.		mm=all	20 25/7 50 250 20
	FOR WHICH PERMISSION IS GRANTED #1	SEWER, ON THE	Tabata eaye
	of Bild n.M.	AVE. TYPE OF STREET	idaso va vidise 1 / L
	THE PREMISES BEING LOT NO 260	ST., House No.	807
	WORK TO BE DONE IN ACCORDANCE WITH		D BY THE CITY CO
7	RULES OF THE DEPARTMENT OF RUBLIC SE	RVICE.	

Note. This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.