## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 7-10-47	FIRST MANHOLE DOWN STREAM 123	
HOUSE NO. 18-1-D. 4		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	5'deep
WAS LATERAL AT CURB?	——————————————————————————————————————	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR A/bri	ght-
SHOW BI DIAGRAM RELATION OF	LATERAL TO WALL OF BUILDING SERVED.	
Sin 9/19-1	Rnook Drive. L	6
Brookside,	Brook Drive- L Acres	
€ #=		No.
	TOWASE STATE TO THE STATE OF TH	- 22.6F
	0	1 47 \= 123 -
SIGNED John Ihm	FILED AT ENGINEER'S	DEFICE 5'dech
INSPECTOR FOR REMARKS:		elisw 9/24/47

Nº 4978

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

Section Section Control	MASSILLON, OHIO,
	RECEIVED OFFEE OF \$
7	The state of the s
13 4	FOR WHICH PERMISSION IS GRANTED
	TO TAP SEWER, ON THE SOULE THE SEWER.
	Activities of the second se
151	OF BUILD LAVE TYPE OF STREET
COP	
	THE PREMISES BEING LOT NO. 12 4 13 HOUSE NO. 17 4
	Dia 100
	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY PASSED BY THE CITY COUNT
	RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
1	A COLOR OF THE DEFARTMENT OF A COLOR OF THE
4	for the state of t
	NAME OF CONTRACTOR - 7

Note. This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.