

N^o 5003

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

5
32
1

DATE INSPECTED 7-31-47

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 300

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE up 33 1/2' 9' Deep
~~STREAM~~ STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

R. J. Snyder
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS: _____

Nº 5003

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 8/5/47

194

RECEIVED OF

Raymond Renley

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

S. Joseph

TO TAP

Sanitary

SEWER, ON THE

East

SIDE

OF

15th St. N.W.

AVE.,
ST.

TYPE OF STREET

City

THE PREMISES BEING LOT No.

17. 86.35. 86.37

HOUSE No.

300

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Raymond Renley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.