FOLLOWING DATA TO BE ANSWERED BY INSPECTOR

DATE INSPECTED_ 6-26 -	AND SIGNED WHEN RETUR	RNED
HOUSE NO	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE OPENS STREAM TO DITCH AT CURB LINE AND DEPTH	7'-6"Deep
WAS LATERAL AT CURB?		1
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Kem	ley
SHOW BY DIAGRAM RELATION O	F LATERAL TO WALL OF BUILDING SERVED.	
SHOW BY DIAGRAM RELATION O	F LATERAL TO WALL OF BUILDING SERVED.	6.6"Deep
	F LATERAL TO WALL OF BUILDING SERVED.	6.6"Deep
	Sed to start 1 Side Walk. 7'-6"Deep "	5 Side Walk of
	F LATERAL TO WALL OF BUILDING SERVED.	6.6"Deep

Book- 9 PAGE 7

Nº 5005

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	Mass	SILLON, OHIO, 5/5/6	194
	ymond Alen	y"	FEE OF \$
TO TAP 300 JULY	ANTED Pacific SEWER ON T	*	SIDE
of Lead E. M.	P		
THE PREMISES BEING LOT NO		, House No	

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNC RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR KOVMONDA A CONTROL

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.