Nº 5012

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8-10-47	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 808	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? Y C 5	NAME OF CONTRACTORAston
SHOW BY DIAGRAM RELATION OF LAT	FERAL TO WALL OF BUILDING SERVED.
	6/ 5' Deep
	b' Deep 16' FE. Curb Line 8th SW.
	EMain Sewer 8 - SW.
SIGNED INSPECTOR FOR CI	FILED AT ENGINEER'S OFFICE 9/9/9/
REMARKS:	

Nº 5012

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

,	RECEIVED OF	Il haten		FEE OF \$	3 42
>		A Alana	ALL B.		•
FOR V	WHICH PERMISSIO	N IS GRANTED			
TO TA	P	SEW SEW	ER, ON THE		
OF	816	AVE., T	YPE OF STREET	Called	
J	,,,			808	

garden grant of the state of th

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.