

N<sup>o</sup> 5020

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

11  
27

DATE INSPECTED 8-23-47

IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM

HOUSE NO. 416

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH

56'6"

8' deep

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes


NAME OF CONTRACTOR

Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Erie St. N.

← N →



?

56'6" 8' deep M.H.

SIGNED John Chesser

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

Nº 5020

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE  
PERMIT TO TAP SEWER

MASSILLON, OHIO,

1947

RECEIVED OF

FEE OF \$

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

SIDE

OF

AVE.,  
ST.,

TYPE OF STREET

THE PREMISES BEING LOT NO.

HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY PASSED BY THE CITY COUNCIL, AND  
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside  
walls of building is subject to Massillon Board of Health Regulations.