

Nº 5031

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

4
20
✓

DATE INSPECTED 9-2-47

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 216

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

171 - 7' deep

WAS LATERAL AT CURB? YES


WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR _____

Aston

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Willow Ave. N.E.



SIGNED _____

John E. Egan
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

9/9/47

REMARKS: _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5031

PERMIT TO TAP SEWER

MASSILLON, OHIO,

7/2

1947

RECEIVED OF

Harvey Astor

FEE OF \$

2⁰⁰

FOR WHICH PERMISSION IS GRANTED

✓ E. E. Jones

TO TAP

Sanitary

SEWER, ON THE

North

SIDE

OF

Willow St. E

AVE.
ST.

TYPE OF STREET

dirt

THE PREMISES BEING LOT No.

7769

House No.

216

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Harry Astor

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.