Nº 5038

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9/22/47	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH GOVERNMENT OF THE PROPERTY OF THE P
WAS LATERAL AT CURB? Ves	
WAS ATTACHED TO MAINSHOW BY DIAGRAM RELATION OF LATE	
	4 -9 - 1= Deel
	60' 62 Deep W. Curb
SIGNED INSPECTOR FOR CITY	FILED AT ENGINEER'S OFFICE 9/23/4/7
REMARKS:	

Nº 5038

* PERMIT TO TAP SEWER

RECEIVED OF	, Massillon, Ohio,	9/22_1947_
OR WHICH PERMISSION IS GRANTED	John Burt	4500
OTAP Sanitary	sewer, on the	ANAS SIDE
11th 11 h	0	pand
HE PREMISES BEING LOT NO	8393-8394 House N	15 09
VORK TO BE DONE IN ACCORDANCE VOLUMES OF THE DEPARTMENT OF PUBLI		PASSED BY THE CITY COUNCIL, AND

AME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.