

Nº 5040

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

$\frac{3}{2}$

DATE INSPECTED 4-30-48

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 318

SIZE OF PIPE USED 6" up DISTANCE FROM FIRST MANHOLE
~~DRAIN~~ STREAM TO DITCH AT 30'
CURB LINE AND DEPTH 6' deep


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Smart.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

11TH ST. S.W.



SIGNED John E. Hines
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 5/12/48

REMARKS: _____

Nº 5040

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE ³/₂₂

PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/30 194

RECEIVED OF Willie Longshore FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED same

TO TAP Sew SEWER, ON THE E SIDE

OF 11th S.W. AVE., TYPE OF STREET Alley
ST.

THE PREMISES BEING LOT NO. 3128, HOUSE NO. 318

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Smart

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.