

N<sup>o</sup> 5049

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED 10-22-97

IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM \_\_\_\_\_

HOUSE NO. 1128

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH

148-

7' deep

WAS LATERAL AT CURB? Yes


WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR

Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Walnut Rd. S.W.



SIGNED

John Elmer  
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

12/1/97

REMARKS: \_\_\_\_\_

Nº 5049

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 10/18 19427  
RECEIVED OF Raymond Remley FEE OF \$ 2.00  
FOR WHICH PERMISSION IS GRANTED Church of God.  
TO TAP San SEWER, ON THE N. SIDE  
OF Walnut St. AVE., TYPE OF STREET Alley  
THE PREMISES BEING LOT NO. 3028, HOUSE NO. 1128

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND  
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

R Remley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.