

14/
28

Nº 5060

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10-15-47

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 65'

8' deep

HOUSE NO. 822

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____


NAME OF CONTRACTOR

Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

32ND ST. N.W.

← N



SIGNED

John E. Evers
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

11/17/47

REMARKS: _____

Nº 5060

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 11/3 1947

RECEIVED OF P. Remley

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Mrs. Geo. Barell

TO TAP San

SEWER, ON THE E

SIDE

OF 32nd Ave.

AVE.,

TYPE OF STREET St.

ST.,

THE PREMISES BEING LOT NO. 9214

HOUSE NO. 822

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Remley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.