

Nº 5069

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

14
18

DATE INSPECTED 10-15-47

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 945

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

162. 7'6 deep

WAS LATERAL AT CURB?


WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Clyde Ct. S W



SIGNED

John E. Chimes
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

12/1/47

REMARKS:

Nº 5069

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 11/13 1947

RECEIVED OF P. Remley

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED W. H. Butz

TO TAP San

SEWER, ON THE S

SIDE

OF Clark St & 8th

AVE.,
ST.,

TYPE OF STREET

THE PREMISES BEING LOT NO. 3145

HOUSE NO. 945

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR P. Remley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.