

Nº 5081

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

$\frac{4}{27}$

DATE INSPECTED 1-20-48

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 100' 10' deep

HOUSE NO. Coal yard.

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH. _____

WAS LATERAL AT CURB? No


WAS ATTACHED TO MAIN No

NAME OF CONTRACTOR Remley.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

3 RD ST. N. W.

← N



SIGNED John E. Shover
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 3/20/48

REMARKS: _____

Nº 5081

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO 1/20 1948
RECEIVED OF Raymond Remley FEE OF \$ 2⁰⁰
FOR WHICH PERMISSION IS GRANTED Marks Laval Co.
TO TAP Sanitary SEWER, ON THE East SIDE
OF 3rd St. H.H. AVE., TYPE OF STREET oiled
THE PREMISES BEING LOT NO. Pt. O.L. 11 HOUSE NO. 116

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Raymond Remley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.