

Nº 5082

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

2
19
✓

DATE INSPECTED 1-20-48

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. Coal yard

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? _____


WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

3 RD ST. N.W.
STORM SEWER.

← N



SIGNED

John Elmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

3/30/48

REMARKS: _____

Nº 5082

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 1/20 1948
RECEIVED OF Raymond Remley FEE OF \$ 2.00
FOR WHICH PERMISSION IS GRANTED Marks Craft Co
TO TAP Storm SEWER, ON THE East SIDE
OF 3rd St N.W. AVE., TYPE OF STREET oiled
ST.,
THE PREMISES BEING LOT NO. Pt. O. L. 11, HOUSE NO. _____

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Raymond Remley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.