FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

N_{\cdot}° 5086	AND SIGNED WHEN RETURNED
DATE INSPECTED 3-8-48	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? YES	NAME OF CONTRACTOR DIAMA
SHOW BY DIAGRAM RELATION OF L	· · · · · · · · · · · · · · · · · · ·
N -	Foundation not started.
8	Deep
62 Deep 8	pprox E. Curb line
	Main Sewer in 3rd S.E.
SIGNED INSPECTOR FOR	Sity FILED AT ENGINEER'S OFFICE 3/30/48

No **5086**

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

- PERMIT TO TAP SEWER

	MASSILLON, OHIO, 2/19	1948
RECEIVED OF John Con	not pee of \$2	<i>UU</i>
FOR WHICH PERMISSION IS GRANTED	Viana	
TO TAP Santany SEWER	R, ON THE last	SIDE
3 mx 11 1/2	PE OF STREET oilea	***
THE PREMISES BEING LOT NO. 8204	, House No	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANC	CE NO. 2323, DULY PASSED BY THE CITY COUNC	CIL, AND

RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.