

N^o 5089

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

7
43
✓

DATE INSPECTED 3-9-48

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1124

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

115' 6' Deep


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

INSPECTOR FOR CITY

R. F. Snyder

FILED AT ENGINEER'S OFFICE

3/24/48

REMARKS:

Nº 5089

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 3/3 1948

RECEIVED OF John Kenny

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED per se

TO TAP San

SEWER, ON THE E

SIDE

OF 3rd SE

AVE., TYPE OF STREET dirt
ST.,

THE PREMISES BEING LOT NO. 8203

HOUSE NO. 1124

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Deana

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.