

Nº 5099

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 4-3-48

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1834

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 34' 6' deep


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Boger

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Jefferson Ave. N.E.



SIGNED John E. Miller
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 4/14/48

REMARKS: _____

Nº 5099

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 3/30 1948

RECEIVED OF D. Boyer

FEE OF 2.00

FOR WHICH PERMISSION IS GRANTED Paul W. Hutcheson

TO TAP San

SEWER, ON THE E

SIDE

OF Jefferson 775

AVE.
ST.

TYPE OF STREET dist

THE PREMISES BEING LOT No. 8103

HOUSE No. 1834

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR D. Boyer

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.