

Nº 5113

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 4-21-48

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 2551

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 133 - 6' deep

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Harsh Ave. S.E.



6' deep
15
9

133

SIGNED

John E. Egan
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 4-21-48

REMARKS: _____

Nº 5113

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 4/10 1922

RECEIVED OF C P Crowl

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Leo Hermann

TO TAP San.

SEWER, ON THE S.

SIDE

OF Harsh St.

AVE., TYPE OF STREET Alled

THE PREMISES BEING LOT NO. Plat 316

HOUSE NO. 2551

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR R. Remley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.