

Nº 5122

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10-18-47

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

50'

8 secp

HOUSE NO. 729

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____


NAME OF CONTRACTOR

Adams.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED

Hill Top PL. S.W.

N →



SIGNED

John Elmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

4/27/48

REMARKS: _____

Nº 5122

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 4/27 1948

RECEIVED OF Robert G Adams FEE OF 2⁰⁰

FOR WHICH PERMISSION IS GRANTED Frank Norton

TO TAP San SEWER, ON THE W SIDE

OF Hilltop Pl S W AVE., TYPE OF STREET dirt

THE PREMISES BEING LOT NO. Out of City HOUSE NO. 729

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR R G Adams & Son

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.

10% add'l Rate.