

Nº 5126

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

2
50-51
✓

DATE INSPECTED 5-17-48

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 159

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

25' 7' deep


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Bemley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

29TH ST. S.E.



SIGNED

John Ehmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

6-28-48

REMARKS: _____

Nº 5126

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO,

1948

RECEIVED OF

C. P. Crowe

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

Same

TO TAP

San

SEWER, ON THE

W

SIDE

OF

27th & E

AVE..
ST..

TYPE OF STREET

Alley

THE PREMISES BEING LOT NO.

3683

HOUSE NO.

159

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Ramsey

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.