

Nº 5130

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

5
54
✓

DATE INSPECTED 5-19-48

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 395' 9' deep

HOUSE NO. 772

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 400' 8' deep


WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Aston

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Matthias Ave N.E.



SIGNED John Ehmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 6-28-48

REMARKS: Tapped on main.

Nº 5130

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 5/13 1948

RECEIVED OF H. J. Astor

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Sheldon Ehmer

TO TAP San

SEWER, ON THE N

SIDE

OF Matthew St.

AVE.,

TYPE OF STREET Residential

THE PREMISES BEING LOT NO. 5250

HOUSE NO. 742

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR H. J. Astor

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.