

N^o 5136

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED


DATE INSPECTED _____

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____HOUSE NO. 1119SIZE OF PIPE USED 4"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH1826' deepWAS LATERAL AT CURB? YesWAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR

Aston

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Green Ave. S.W.

SIGNED

John E. Evers
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

6-1-48

REMARKS:

from W. Curb line of 1124 ST S.W.

Nº 5136

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 5/25 1948
RECEIVED OF R B Herman FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED same

TO TAP San. SEWER, ON THE S. SIDE
OF Green St. W. AVE., TYPE OF STREET Alley
ST.,

THE PREMISES BEING LOT NO. 3016 HOUSE NO. 1119

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR H. Aston

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.