


N^o 5137

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5-27-48IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____HOUSE NO. 909SIZE OF PIPE USED 6" upDISTANCE FROM FIRST MANHOLE
~~DOWN~~ STREAM TO DITCH AT
CURB LINE AND DEPTH 21'5' deepWAS LATERAL AT CURB? YesWAS ATTACHED TO MAIN YesNAME OF CONTRACTOR Diapa

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Benington Ave N.E.

SIGNED

John Chesser
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

6-2-48

REMARKS: _____

N^o 5137

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

RECEIVED OF A. Mallalieu MASSILLON, OHIO. 5/27 1948
 FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

Marvin Larson

TO TAP

San

SEWER, ON THE

A.

SIDE

OF

Bennington E.AVE.
ST.

TYPE OF STREET

Alley

THE PREMISES BEING LOT NO.

Plt 8536-37

HOUSE NO.

909

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
 RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

A. J. Deane

Note. This permit covers work outside of building only. Any work inside
 walls of building is subject to Massillon Board of Health Regulations.