

4-6

N^o 5141

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 6-5-48IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____HOUSE NO. 831SIZE OF PIPE USED 6"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 89' 7' deepWAS LATERAL AT CURB? YesWAS ATTACHED TO MAIN YesNAME OF CONTRACTOR Aston

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lake Ave NE

SIGNED

John Ehmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

6-17-48

REMARKS:

found 4" under walk.

Nº 5141

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 5/29 1948

RECEIVED OF H. Aston

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Paul Engleman

TO TAP San

SEWER, ON THE S.

SIDE

OF Lake N-E

AVE., TYPE OF STREET Alled
St.,

THE PREMISES BEING LOT NO. 4047

HOUSE NO. 831

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR H. Aston

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.