

6-15

Nº 5142

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6/3/48

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1126

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 29' 9' deep

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____


NAME OF CONTRACTOR Bemley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

LAKE Ave

N. →

LAKE Ave



WAYLES Rd.

SIGNED

John Ehmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

6-17-48

REMARKS: _____

Nº 5142

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 4/1

1948

RECEIVED OF R. Remley

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Fred Heibel

TO TAP San

SEWER, ON THE 7th

SIDE

OF Lake St.

AVE.,
ST.,

TYPE OF STREET Relief

THE PREMISES BEING LOT No. 5320

HOUSE No. 1126

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Remley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.