

Nº 5151

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 7-20-48

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 60

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

70- 5' deep

WAS LATERAL AT CURB? No


WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Goose Ave N.W.



SIGNED

John E. Turner
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

7-24-48

REMARKS:

Nº 5151

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 6/23 1948

RECEIVED OF

Frank Furante

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

panel

TO TAP

San

SEWER, ON THE

N.

SIDE

OF

Groove NW

AVE.,
ST.,

TYPE OF STREET

driv

THE PREMISES BEING LOT NO.

Pl. 3566

HOUSE NO.

60

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Diana

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.