FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 7-23-48	IF SO HOW AND LOCATION FROM	>
HOUSE NO. 154	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	10 Deep
WAS LATERAL AT CURB? Yes	Dian	(
WAS ATTACHED TO MAINSHOW BY DIAGRAM RELATION OF LAT		
7 Pipe from Curba	to 45° Bend	Foundation not started.
40' " Bend	to house 5 Li Dee	P
	5) 10' Deep	Approx E. Curb Line
	160'	Mainsewer in 20-31
SIGNED INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE_	J. J
REMARKS:		

5167 N_{i}^{o}

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	*	Massillon, Ohio,	1/22	1948
RECEIVED OF	A De	nd	FEE OF	200
FOR WHICH PERMISSION IS GRA	NTED AUL	17	11 1/2 1/2	
TO TAP		ON THE	6	SIDE
20 16	15		first	
	6279	, House No	154	
WORK TO BE DONE IN ACCORDA	ANCE WITH ORDINANC	E No. 2323. DULY, F	PASSED BY THE CIT	Y COUNCIL, AND
THE PREMISES BEING LOT NO	6279		PASSED BY THE CITY	Y Council

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.