FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

	DATE INSPECTED 7-31-48 IF SO HOW AND LOCATION FROM 42 8 DEEP
	HOUSE NO. ZZ Rawson SE upstream
	SIZE OF PIPE USED DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH #2 7 Deep
	WAS LATERAL AT CURB? NO
ų	WAS ATTACHED TO MAIN TAPPED. NAME OF CONTRACTOR
3	SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
† V)	Total Length L'pipe 160'
<u>بر</u>	of pipe 160
YW5	Z Z Z
Ž	
	SIGNED R. T. MANUELLE AT ENGINEER'S OFFICE
	REMARKS: House Jaces on Rauson but sever latural
	had to the run walnut S.E.

 N_0

5168

N? $51\overline{6}8$

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, OHIO,_	7/30 1048
Por a se	Lacon, Onio,	FEE OF S 2 U
RECEIVED OF	mie Exam	THE OF SE
FOR WHICH PERMISSION IS GRANTED		an th
D Walnut Ru.	SEWER ON THE	side side
OFAVE.	TYPE OF STREET	oued.
THE PREMISES BEING LOT NO. 428	House No	, 22 Kawam

RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Julies Carly

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.