FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

· · · · · · · · · · · · · · · · · · ·	
DATE INSPECTED 8-13-5	FIRST MANHOLE DOWN STREAM 274
HOUSE NO. 2935	z nd
SIZE OF PIPE USED	DISTANCE FROM PHRSE MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 274' 10' de est
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN Yes	NAME OF CONTRACTOR Albrecht
SHOW BY DIAGRAM RELATION OF	LATERAL TO WALL OF BUILDING SERVED.
Lincoln	Way, N.W.
	740-7
4	7. √ 1
	10'00
	2/4-8
1 1 9	CUPB LINE
SIGNED COM	FILED AT ENGINEER'S OFFICE 8/17-48
INSPECTOR FO	R CITY
REMARKS: FIYS & M. H. A	own stream is under the corner of the

No

5171

offset in sidewalk. This dist. 125 from M.H. to Lat. at Curb.

Nº 5171

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	8/5-
S P D MASS	sillon, Ohio, 1940
RECEIVED OF	FEE OF \$
FOR WHICH PERMISSION IS GRANTED	harquiet Jimmer
TO TAP Landay SEWER, ON T	HE_South SIDE
to the AM AVE. THOUSE	STREET_Phyl 14
THE PREMISES BEING LOT NO. 2935 /23	21. House No. 2 12931
THE PREMISES BEING LOT NO.	L. House No.

RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR K. Willy cht

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.