

Nº 5177

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

7
23

DATE INSPECTED 8-18-48 IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 27 - 9' deep

HOUSE NO. _____

SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____


WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

23 RD S.T. N.W.



SIGNED

John Ehrner
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

8-27-48

Dec

REMARKS: _____

Nº 5177

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

5⁵⁰ rate

8/18

MASSILLON, OHIO,

1948

RECEIVED OF

H. A. O'Neil

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

Same.

TO TAP

San.

SEWER, ON THE

W

SIDE

OF

23rd NW Ept

AVE.,
ST.,

TYPE OF STREET

driv

THE PREMISES BEING LOT NO.

11984

HOUSE NO.

587

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

A. J. Quinn

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.